





➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries

<div>   </div>		NMSU 2016 ADA Assessment Phase 1 January 2017	
Building #:		363	
Building Name:		Engineering Complex I	
Drawing Title:		First Floor Plan	





➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries

<div>   </div>		NMSU 2016 ADA Assessment Phase 1 January 2017	
Building #:		363	
Building Name:		Engineering Complex I	
Drawing Title:		First Floor Plan	



➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries



NMSU 2016 ADA Assessment
Phase 1
January 2017

Building #:	363
Building Name:	Engineering Complex I
Drawing Title:	First Floor Plan



➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries

<div><div><div>NM STATE UNIVERSITY</div><div>arc</div></div><div><div>NMSU 2016 ADA Assessment</div><div>Phase 1</div><div>January 2017</div></div></div>	
Building #:	363
Building Name:	Engineering Complex I
Drawing Title:	First Floor Plan