






Primary Accessible Entry



/ [NMSU 2016 ADA Assessmen
I E		Phase 1
SITY	∕arc_	January 2017


Building #:	056		
Building Name:	Dove Hall		
Drawing Title:	Second Floor Plan		



→ Primary Accessible Entry



NM STATE UNIVERSITY	∕arc_	NMSU 2016 ADA Assessment Phase 1 January 2017
Building #:		056
Building Name:		Dove Hall
Drawing Ti	tle:	Second Floor Plan
		APC Project# 21610



Primary Accessible Entry



NM STATE UNIVERSITY	NMSU 2016 ADA Assessment Phase 1 January 2017
Building #:	056
Building Name:	Dove Hall
Drawing Title:	Second Floor Plan