







➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries

|  |                   |
|--|-------------------|
| <div>   </div> <div> <div>NMSU 2016 ADA Assessment</div> <div>Phase 1</div> <div>January 2017</div> </div> |                   |
| Building #:  | 551               |
| Building Name:   | Skeen Hall        |
| Drawing Title:   | Second Floor Plan |



➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries

|   |                   |
|---|-------------------|
| <div><div><div>NM STATE UNIVERSITY</div><div>arc</div></div><div><div>NMSU 2016 ADA Assessment</div><div>Phase 1</div><div>January 2017</div></div></div> |                   |
| Building #:   | 551               |
| Building Name:  | Skeen Hall        |
| Drawing Title:  | Second Floor Plan |