

278.68-69

278.17

278.20

➔ Primary Accessible Entry




ADA Compliant Exterior Public Entries

NON ADA Compliant Exterior Public Entries



Reference Drawing - Not to Scale

	NMSU 2016 ADA Assessment Phase 1 January 2017	
Building #:	278	
Building Name:	Branson Library	
Drawing Title:	Fourth Floor Plan	





➔ Primary Accessible Entry



ADA Compliant Exterior Public Entries

NON ADA Compliant Exterior Public Entries

<div>   </div>		NMSU 2016 ADA Assessment Phase 1 January 2017	
Building #:		278	
Building Name:		Branson Library	
Drawing Title:		Fourth Floor Plan	



➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries



NMSU 2016 ADA Assessment
Phase 1
January 2017

Building #:	278
Building Name:	Branson Library
Drawing Title:	Fourth Floor Plan



➡ Primary Accessible Entry



ADA Compliant Exterior Public Entries



NON ADA Compliant Exterior Public Entries







NMSU 2016 ADA Assessment
Phase 1
January 2017

Building #:	278
Building Name:	Branson Library
Drawing Title:	Fourth Floor Plan



➡ Primary Accessible Entry

-  ADA Compliant Exterior Public Entries
-  NON ADA Compliant Exterior Public Entries

<div>  <div> NMSU 2016 ADA Assessment Phase 1 January 2017 </div>  </div>	
Building #:	278
Building Name:	Branson Library
Drawing Title:	Fourth Floor Plan